



State of Connecticut **ACCIDENT INFORMATION SUMMARY**

CFS #: 2300302526

Department of Emergency Services and
Public Protection / Division of State Police

Date: 07/26/2023

Time: 16:12

State Police Troop: TRAFFIC SERVICES


Primary Officer: HACKETT, RYAN J

Location: Wire Mill Rd Stamford

Intersection: Studio Road

Involved Vehicles

Vehicle #: 1
Owner: City Of Stamford Police Department **Address:** 725 Bedford St Stamford Ct
Plate: 296ST **State:** CT **Make:** Ford **Model:** Explorer **Year:** 2017
Vin: 1FM5K8AR0HGC08020 **Insurance Co.:** SELF - CITY OF STAMFORD **Policy #:** CT N/A
Vehicle Towed: Yes **Towed To:** State Police - Troop G
Damaged Area: Sector 2 (NorthEast) in the 12-point Clock Diagram None None



Vehicle Damage Diagram

Involved Persons

Name: Jackson, Tommie **Sex:** M **D.O.B.:** 01/18/1954 **OP State & No.:** CT 137243313

Address: 458 Wire Mill Rd Stamford Ct

Status: Pedestrian

Seating Position:

Protection System:

Airbag Status:

Injuries: Fatal Injury

Transported: Yes **Transported By:** Stamford EMS

Hospital: STAMFORD HOSPITAL

Vehicle #: 1 **Name:** Lockwood, Zachary Thomas **Sex:** M **D.O.B.:** 02/12/1999 **OP State & No.:** CT 029184720

Address: 725 Bedford St Stamford Ct

Status: Driver

Seating Position: Front Left(usually the motor veh or motorcycle driver except for postal vel

Protection System: Unknown

Airbag Status: Not Deployed

Injuries: No Apparent Injury

Transported: Yes **Transported By:** Stamford EMS

Hospital: GREENWICH HOSPITAL

On 07/26/2023 at approximately 1612 hours, a 2017 Ford Interceptor Utility, operated by Stamford Police Officer Zachary Lockwood (DOB: 02/12/1999) was traveling eastbound on Wire Mill Road in the City of Stamford. In this area of Wire Mill Road, a right curve is present.

At this time, a pedestrian, identified as Tommie Jackson (DOB: 01/18/1954), was on foot northbound, attempting to cross the roadway after retrieving mail from a mailbox. Upon observing Jackson, Lockwood made an evasive steering maneuver, entering into the westbound lane. While within the westbound lane, the Ford Police Interceptor Utility collided into Jackson. Following impact, the Ford Police Interceptor Utility entered onto the property of 458 Wire Mill Road. As a result of the collision, Jackson sustained fatal injuries.

At the request of Stamford State's Attorney's Office, the State Police - Western District Major Crime Squad, in conjunction with the Collision Analysis and Reconstruction Squad, assumed the investigative responsibility of the collision. Anyone who may have witnessed this collision or the moments prior to the collision are asked to contact Detective Corey Clabby at corey.clabby@ct.gov or Detective Ryan Hackett at ryan.hackett@ct.gov.

SUPERVISOR SIGNATURE AND BADGE NO.

/LT MARK J DICOCO/ 0039

DATE SIGNED

07/26/2023